


CODE: P432091
Item: END CAP ZIK 16-25

INSTALLATION MANUAL

1.	Select the cable to be terminated with insulation cap.	
2.	Place the insulation cap on the end of the cable for termination. By pressing the cap and screwing as shown on the picture right, install the cap on the end of the cable. This will provide insulated termination of the cable and prevent penetration of the moisture and dust on the cable's conductor.	
3.	After followed previous steps, insulation cap is now installed on the end of the cable.	

LEGAL NOTICE:

The product must be installed only by a competent trained person with installation practices and with sufficient knowledge of good safety and installation practices in respect of electrical equipment. PLAMEN accepts no liability concerning claims resulting from misuse, incorrect installation or ignored national safety regulations or other national provisions. Failure to follow the installation instructions may result in damage to the product and serious or fatal injury.

