






CODE: P41242X, D41242X
Item: PG Connectors UNIMAX AL /Cu

INSTALLATION MANUAL

<p>1. Before connector installation, it is recommended to clean the conductors with steel brush of dirtiness and/or dust.</p>	
<p>2. Unscrew bolts of PG connector to have enough space to place conductors into clamp.</p>	
<p>3. Place the conductors (branch and main) in the parallel grooves of the connector as shown on the picture.</p>	
<p>4. Screw the bolts of PG connector with adequate wrench till rated torque value which is designated on the PG connector.</p>	 <p style="text-align: right;">13 mm</p>
<p>5. PG connector is now ready for exploitation.</p>	



LEGAL NOTICE:

The product must be installed only by a competent trained person with installation practices and with sufficient knowledge of good safety and installation practices in respect of electrical equipment. PLAMEN accepts no liability concerning claims resulting from misuse, incorrect installation or ignored national safety regulations or other national provisions. Failure to follow the installation instructions may result in damage to the product and serious or fatal injury